

## **Clermont and Montrose Avenues**

### General Comments:

None

### Specific issues by Station Number:

215+50	Remove Spruce tree – declining health. Not a desirable species. Committee recommends removal. Removal of tree will allow for replacement tree better suited for location.
213+00	Remove large Tulip Poplar. Not a desirable species. Committee recommends removal. Removal of tree will allow for replacement tree better suited for location.
210+50	Large Willow Oak – move tree root bridge further from tree.
209+50	Large Willow Oak – recommend tree root bridge.
208+50	Large Willow Oak – recommend tree root bridge.
207+50	Large Willow Oak – recommend tree root bridge.
206+00	Red Maple – additional tree root bridge to protect Red Maple located closest to Town Right-of-way.
203+00	Move tree root bridge further away from tree

## **Kenilworth Avenue**

104+00	Recommend moving sidewalk inside (away from road) Town tree – as far as possible from tree.
105+00	Tree root bridge recommended for Japanese Red Maple.
105+50	Move sidewalk inside Town red maple (tree root bridge to be added for this tree). Also, removal of Photinia shrub recommended.
106+50	Red Maple – add tree root bridge.
107+00	No need to “jog” sidewalk. Removal of scrub bushes and invasives is recommended (bush honeysuckle, etc.)
108+00	Willow Oak - add tree root bridge.

## **Oxford Street**

- |        |   |
|--------|---|
| 402+00 | Removal of both Katsura trees recommended. Both have been decimated by PEPCO line work and will continue to be pruned by PEPCO. Power line issues; we will recommend more suitable trees for this site. |
| 300+50 | Move sidewalk further from road and tree if possible. Tree root bridge may be necessary if moving sidewalk is not an option.  |
| 301+00 | Removal of small Red Maple recommended.   |
| 301+00 | Tree root bridge recommended for larger tree (possible removal if during tree root bridge construction decay in roots is found).  |
| 303+00 | Tulip Poplar – tree root bridge recommended.  |
| 305+50 | Removal of Pin Oak recommended (declining health). Replacement tree will be recommended for site.   |
| 309+50 | Tree root bridge recommended for Japanese Maple.  |
| 310+00 | Tree root bridge recommended for Japanese Maple.  |
| 311+00 | Tree root bridge recommended for Ash Tree.  |
| 313+50 | Removal of Red Maple recommended – declining health and not a valuable species.   |